



SURE GRIP BELT CLAMP



MARK 3 OPERATING PROCEDURE

Patent No. US 6068318 • AU 740976

MARK 3 MAXIMUM SCREW TENSION 160 N/M

ISOLATION

1. Ensure the conveyor belt is fully isolated and tagged out to the mines ISOLATION PROCEDURE.
2. Select position where clamp/clamps are to be used, clean belt of all forms of dirt, moisture and oils etc, unscrew both clamp bolts, remove end assemblies and separate the beams.
3. Position the bottom beam under the belt and support each end, **ensuring it is 90 degrees to the belt.**
4. Place the top beam into position, slide the end clamps over the top and bottom beam and ensure that clamps are placed against each edge of the conveyor belt.
5. If using a torque wrench ensure the correct pressure is applied to the tensioning bolts to ensure maximum clamping force. **(It is not necessary to over tighten main screw as 160 N/M applies a force of 3.5 tonnes).**
6. Connect the pulling appliances to the lugs of the clamps and tension until sufficient slack belt has been obtained. When two appliances are used, **operate them together and evenly.**
7. When clamps are butted up against stops or structure the supports should be no more than 30mm from each edge of the belt.
8. To remove the clamps when the belt repair is finished reverse the above procedure. Release all clamp bolts allowing tension in the belt to dissipate.
9. Remove the clamps and your danger tags once the belt is re-tensioned and ready to start.



MARK 3

OPERATING PROCEDURE

SURE GRIP MARK 3 BELT CLAMP

STORAGE

Clamps should be stored in the assembled position, to avoid damage and loss of items.

Torque 160 N/M = 54kg applied to 300mm spanner

Coefficient of friction = 0.14 on main screw

Force per clamp = 3.5 tonnes

Total clamp force on belt = 7 tonnes

Total force at belt creep = 14 tonnes = 2 – 1 safety factor
= W.L.L.* of 7 tonnes

BELT TYPE

12000 k/n x 4 ply x 4 & 2 covers, FRAS Rubber

* = Work Load Limit

